EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	196	lithographic adj (mask masks) with (fabricate fabrication)	USPAT	OR	OFF	2006/09/29 17:35
L2	3	lithographic adj (mask masks) with (fabricate fabrication) with known	USPAT	OR	OFF	2006/09/29 18:07
L3	0	(memory memories) and redundant and repair adj signature and container	US-PGPUB; USPAT	OR	OFF	2006/09/29 18:08
L4	848	(memory memories) and redundant and signature and container	US-PGPUB; USPAT	OR	OFF	2006/09/29 18:08
L5	1	((memory memories) and redundant and signature and (container fuse)).clm.	US-PGPUB; USPAT	OR	OFF	2006/09/29 18:09
S1	1968	(365/200-201.ccls. 714/710,718. ccls.) and (fuse fuses)	USPAT	OR	OFF	2006/09/28 20:04
S2	132	(365/200-201.ccls. 714/710,718. ccls.) and (fuse fuses) near (bank)	USPAT	OR	OFF	2006/09/29 14:54
S3	4	(365/200-201.ccls. 714/710,718. ccls.) and (fuse fuses) near (bank) and multiple near (array arrays macro macros)	USPAT	OR	OFF	2006/09/28 20:14
S4	25	("4228528" | "5270976" | "5323348" | "5377146" | "5430679").PN. OR ("5532966"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/09/28 20:10
S5	37	(365/200-201.ccls. 714/710,718. ccls.) and (fuse fuses) and multiple near (array arrays macro macros)	USPAT	OR	OFF	2006/09/28 20:14
S6	38	(365/200-201.ccls. 714/710,718. ccls.) and (fuse fuses) near2 (shared share)	USPAT	OR	OFF	2006/09/29 11:56
S7	4	(365/200-201.ccls. 714/710,718. ccls.) and (fuse fuses) with signature and register	USPAT	OR	OFF	2006/09/29 12:00
S8	1	714/710.ccls. and (fuse fuses) with signature and register	USPAT	OR	OFF	2006/09/29 12:00
S9	18	("20030026147" | "20040136257" | "5325334" | "5337277" | "5359560" | "5596536" | "5796750" | "5831916" | "5999463" | "6067268" | "6249465" | "6295627" | "6505324" | "6598190" | "6603690" | "6704227" | "6757204" | "6973605").PN. OR ("7093156"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/09/29 12:00

EAST Search History

S10	6	("4355376" | "5901095").PN. OR ("6249465").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/09/29 14:53
S11	0	(365/200-201.ccls. 714/710,718. ccls.) and (fuse fuses) near (bank) with (compress compression compressing compressed)	USPAT	OR	OFF	2006/09/29 14:54
S12	11	(365/200-201.ccls. 714/710,718. ccls.) and (fuse fuses) with (compress compression compressing compressed)	USPAT	OR	OFF	2006/09/29 14:54